

<b>From:</b>	Silva, Sathya </O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=6085003A5604409C83A2BA13C65D18B9-SILVA SATHY>
<b>To:</b>	Farmiga Sam (b)(6) <(b)(6)>
<b>Subject:</b>	FW: Information require
<b>Date:</b>	2022/04/21 08:15:00
<b>Priority:</b>	Normal
<b>Type:</b>	Note

Sam, would you be able to get me the information below, please?

**Sathya S. Silva, Ph.D.**

*Senior Aviation Accident Investigator/ Investigator in Charge (IIC)*

*Major Investigations Division*

*National Transportation Safety Board*

*490 L'Enfant Plaza East, SW, Washington, DC 20594*

(b)(6)

(b)(6)



*NTSBSeal\_letter*

*NTSB 24-hr Response Operations Center (202) 314-6290*

**From:** 林航 &lt;(b)(6)&gt;  
**Sent:** Wednesday, April 20, 2022 10:18 PM  
**To:** Silva, Sathya &lt;(b)(6)&gt;  
**Cc:** 李勇 &lt;(b)(6)&gt;  
**Subject:** Information require

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hi Sathya,

Information is needed as follow,

More detailed list of engine parts installed with piece/serial numbers is required from NTSB to confirm the corresponding location of the parts in the left and right engines.

Many thanks.

Lin

Director, Accident Investigation Division, AS, CAAC

155, West Dongsì St. Beijing, China

100710

Mail (b)(6)

Tel: (b)(6)